

Technical Bulletin

Magellan 8400 Scanner/Scale — New Firmware Required for New Load Cell

SS-TECH-10:04
February 3, 2010

Datalogic has made a change to the load cell that is used in Magellan 8400 scanner/scales with a manufacturing date of 12/1/2009 or later. This change affects operation with some POS systems.

Note: the manufacturing date can be located and read by lifting the platter and checking the label.

SCANMASTER

The following firmware and configuration files must be used for the Magellan 8400 with the new load cell to operate properly with ScanMaster. The current firmware and flash files that were initially released will not work on the newer scanners. The firmware and configuration files are available from StoreNext on the StoreNext Dealer Support Web site using the link below:

<ftp://ftp.storenext.com/iss45support/Datalogic/Firmware/8400/>

(This link can also be located from the Support Page by selecting the Drivers and Firmware Page.)

Note that this new firmware may be used on 8400 scanner/scales with the original load cell (manufacturing date prior to 12/1/2009) but it is *not* necessary to update these earlier scanners already working in the field.

ISS45

The new firmware may be used on 8400 scanner/scales but it is *not* necessary to update scanners already working in the field.