

**Subject: TP3K XE Port Switch Label Incorrect in I&M Manual (D900000171).**


**Issue:**

TP3K XE Port switch label is incorrect in the Installation and Maintenance Manual (D900000171), section: 1.1 page 17 of 135 .

**Solution**

All corrections will be made on the next scheduled update to the manual.

**Corrections to be made in RED:**



<u>INQUIRIES TO:</u>		DATE
Fujitsu Transaction Solutions Inc.		
Exchange:	Sustaining Engineering	_____
Mail:	Fujitsu USA04, Sustaining Engineering	_____
FAX:	858-731-4781 (7888-4781)	_____
Internet:	<a href="mailto:SustainingEngineering@ftxs.fujitsu.com">SustainingEngineering@ftxs.fujitsu.com</a>	_____
FTP:	<a href="ftp://ftp.ftxs.fujitsu.com/">ftp://ftp.ftxs.fujitsu.com/</a>	_____
Original signature copies maintained by Sustaining Engineering.		