



Subject: New Bill Acceptor I/F Cable for Genesis U-Scan

Overview

The current TP3K MFL Bill Acceptor Interface Cable has been redesigned to accommodate the TeamPoS 3600 and TPX-II Controller(s).

Problem

Existing cable will not support TeamPoS 3600 or TPX-II controllers

New Cable design P/N: 11003529 can only work with the new F53 Power Supply Interface Cable P/N: 11003534

Solution

New systems using a TeamPoS 3600 or TPX-II controller will need cable P/N 11003529 plus the F53 Power Supply I/F cable P/N 11003534.

Part Number	Description	Superseded By
11002138	CBL ASSY, TP3K Port 4, RS-232 - Cashcode Bill Acceptor MFL Front Load, 2.5meters	11003529 + 11003534

Impact

- Production
 - Standard cut-in. Use up existing inventory of 11002138 on Genesis with controllers other than TP3600 or TPX-II.
- Installed Units
 - If stock of old cable (P/N 11002138) is unavailable for older controllers, replace with new cables (P/N's 11003529 and 11003534)
- Repair Center
 - N/A
- Service Spares
 - Use up existing inventory of 11002138 for older controllers. Purchase new cables for existing install base and replenishments of 11002138 stock.

INQUIRIES TO:		DATE
Fujitsu Frontech North America		
Exchange:	Sustaining Engineering	_____
Mail:	Fujitsu USA20, Sustaining Engineering	_____
FAX:	(949) 458-6257	_____
Internet:	SustainingEngineering@us.fujitsu.com	_____
FTP:	ftp://ftp.ftxs.fujitsu.com/Pos/PosSustaining/	_____
Original signature copies maintained by Sustaining Engineering.		