

Subject: TeamPoS CD-RW/DVD Drive Replacement

Overview

The CD-RW/DVD drive that is used in various POS terminals has gone EOL and is being replaced.

Terminals affected:

TeamPoS 3000 XL	No Replacement Drive
TeamPoS 3000 XL2	Replacement Drive Released
TeamPoS 3600	Replacement Drive Released
TeamPoS 7000 F-Series	Replacement Drive Released

Parts Affected:

Current Drive:	11004067
Replaced By:	CP557625

The above replacement drive is supported by all the above terminals EXCEPT the TeamPoS 3000 XL. For the XL terminal, a last time buy must be placed for the current drives to support that install base through its EOL.

Impact

- Production Change to new drive as inventory is consumed.
- Installed Units No Impact.
- Repair Center No Impact.
- Service Spares
 - Reserve all 11004067 spares for use on TeamPoS 3000 XL units only.
 - Purchase new part number for all future orders.

<u>INQUIRIES TO:</u>		DATE
Fujitsu Frontech North America		
Exchange: Sustaining Engineering	_____ Sustaining Engineering	_____
Mail: Fujitsu USA20, Sustaining Engineering	_____	_____
FAX: (949) 458-6257	_____ Product Manager	_____
Internet: SustainingEngineering@us.fujitsu.com	_____	_____
FTP: ftp://ftp.ftxs.fujitsu.com/Pos/PosSustaining/	_____ Author	_____
Original signature copies maintained by Sustaining Engineering.		