



**Subject: New CashCode Firmware US1735 - USA**

**Overview**

A new release of firmware for the CashCode Bill Acceptor has been released to support the release of the new US \$100 note.

Part Number	Description	Comments
11002443	Program Stick, US1731, 50 Loads (USA)	Replaced by 11004678
11004678	Program Stick, US1735, 50 Loads (USA)	

For customers that accept ASM software updates, this firmware update is also available via an ASM package. Contact your SDM for details. The CashCode unit must have the Fujitsu Memory Stick (labeled C05) in order to accept these software downloads. This memory stick is standard in Fujitsu supplied units.

**Limitations:**

The current \$100 note has an acceptance rate of 30% when inserted with the face up and head on left. All other insertion orientations for the current \$100 note have an acceptance rate of 98% or greater. The new \$100 note and all other US notes have an acceptance rate of 98% or greater in all insertion orientations.

**Impact**

- Production Cut in upon stock depletion of current stock.
- Installed Units Fit-On-Fail or as requested only.
- Repair Center Any US CashCode devices returned for repair should be updated to the latest firmware.
- Service Spares None.

<b>INQUIRIES TO:</b>		DATE
Fujitsu Frontech North America		
Exchange:	Sustaining Engineering	_____
Mail:	Fujitsu USA20, Sustaining Engineering	_____
FAX:	(949) 458-6257	_____
Internet:	<a href="mailto:SustainingEngineering@us.fujitsu.com">SustainingEngineering@us.fujitsu.com</a>	_____
FTP:	<a href="ftp://ftp.ftxs.fujitsu.com/Pos/PosSustaining/">ftp://ftp.ftxs.fujitsu.com/Pos/PosSustaining/</a>	_____
Original signature copies maintained by Sustaining Engineering.		