

## Update Bulletin

### **Fujitsu TeamPoS 3000 XE with Legacy I/O Board — Withdrawn for ScanMaster Installations**

March 25, 2009

The Fujitsu TeamPoS 3000 XE with the “Legacy” I/O cannot properly support ScanMaster.

StoreNext knows of no installations of ScanMaster with XE Legacy. This configuration is withdrawn and no support will be available for this combination.

There are no known issues with the standard P-USB version of the TeamPoS 3000 XE, or with any configurations of the TeamPoS 3000 XL with ScanMaster. The withdrawn ScanMaster configuration is the TeamPoS 3000 XE Legacy I/O only.

To Your Success,



---

*Anthony van Seester*

This document and information are supplied to StoreNext Retail Technologies personnel and third parties to assist them in doing business with StoreNext. They are not to be used or distributed for any other purpose.

StoreNext Retail Technologies LLC endeavors to ensure that the information in this document is correct and fairly stated, but does not accept liability for any error or omission.