



 Release Notes & What's New

 ISS45 8.1.8.1-160



ISS45 Release Notes

Date of Issue	Product ID Num.	Part Number	Brief Description
January 2005	45001/081	89000195	Initial Release
Other Releases: 89000233, 89000263, 89000263, 89000308, 89000308, 89000401, 89000417, 89000416, 89000480, 89000490, 89000508, 89000521, 89000532, 89000547, 89000573, 89000583, 89000587, 89000590, 89000613, 89000641, 89000658, 89000683, 89000692, 89000693, 89000712, 89000720, 89000734, 89000737, 89000740, 89000747, 89000748, 89000758, 89000767, 89000782, 89000791, 89000792, 89000793, 89000794, 89000796, 89000812, 89000815, 89000822, 89000825, 89000854, 89000861, 89000862, 89000863, 89000872, 89000873			
September 2016	45001/081	89000877	8.1.8.1-050 Release
December 2016	45001/081	89000887	8.1.8.1-060 Release
April 2017	45001/081	89000888	8.1.8.1-070 Release
June 2017	45001/081	89000889	8.1.8.1-080 Release
August 2017	45001/081	89000890	8.1.8.1-090 Release
September 2017	45001/081	89000893	8.1.8.1-100 Release
December 2017	45001/081	89000894	8.1.8.1-110 Release
March 2018	45001/081	89000903	8.1.8.1-120 Release
March 2018	45001/081	89000904	8.1.8.1-120 Release (Updated)
July 2018	45001/081	89000930	8.1.8.1-130
September 2018	45001/081	89000931	8.1.8.1-140
February 2019	45001/081	89000934	8.1.8.1-150
March 2019	45001/081	89000936	8.1.8.1-160

©Copyright NCR Corporation 1995-2019
All rights reserved

This publication is protected by federal copyright law. This document and its contents are the proprietary, confidential information and property of NCR Corporation ("NCR"). Unauthorized disclosure, reproduction, distribution or use of this document and/or its contents in any form is strictly prohibited. No part of this publication may be reproduced or transmitted into any human or computer language in any form or by any means, stored in a retrieval system, transmitted, redistributed, translated or disclosed to third parties, or de-compiled in any way including, but not limited to, photocopy, photograph, electronic, mechanical, magnetic or manual without the express written permission of NCR or its licensors, if any. This document, notwithstanding the above, may be distributed in electronic or printed form by NCR to personnel who are employed by either (a) a licensee and end user of the subject system of this document or (b) personnel from an authorized NCR Channel Partner or Solution Provider of the subject system of this document. All copies of this document so distributed and/or so authorized, shall contain a full copy of this copyright notice.

NCR has prepared this document as a guide to the proper installation, operation, customization and/or maintenance of NCR products. The drawings and specifications contained herein are the property of NCR and/or its licensors.

NCR endeavors to ensure that the information in this document is correct and fairly stated but does not accept liability for any error or omission. NCR makes no representation or warranties with respect to the contents hereof, and specifically disclaims any implied warranties of merchantability or fitness for a particular purpose or non-infringement. No commitments by NCR or its suppliers are made by or from this documentation which is provided for information only.

Development of NCR products and documentation is continuous: NCR reserves the right to revise this publication and to make changes at any time to the contents hereof or to the products herein described or discussed without notice and without any obligation for NCR to notify any person or organization of such revision or changes. Information published in this document will likely be superseded, and it is recommended that users regularly check for updates and newer versions.

The trademarks NCR, Retalix, StoreNext, ISS45, ScanMaster, R10, ACS, PocketOffice, RPO, RBO, ABO, Connected Payments, ServerEPS, Connected Services, Connected Loyalty, WinEPS and all other NCR product names are registered trademarks or trademarks of NCR; all other trademarks or registered trademarks are the property of their respective owners. Third-party products, services, or company names referenced in this document may be trademarked or copyrighted by their respective owners, and are for identification purposes only. Copyrights, trademarks and license agreements shall be governed and construed in accordance with the laws of the State of New York and the Federal Arbitration Act, and shall benefit NCR, its successors, and assigns.

Address comments and corrections regarding this document to NCR Support at the address normally used.

Contents

Introduction	1
Certification of the ADK 6.1.2 SSCO with the R6L and R6C hardware	2
ISS45-1274 – Validate MTX Dlls.....	3
ISS45-1488 – Apply Windows Updates	3

Introduction

Enhancements were recently made to the ISS45 system. The changes are reflected in the accompanying ISS45 8.1.8.1-160 software.

Following the change description is an abbreviation (or combination thereof) of the ISS45 area affected:

- POS – WinPOS
- SSCO – Self-Service Check-Out

These enhancements are explained in detail in the following pages, and are not included in the latest Office Users Guide, WinPOS User Guide or Office Administrator's Reference. If you have any questions regarding this release, please contact NCR Support.

Certification of the ADK 6.1.2 SSCO with the R6L and R6C hardware

With the release of the 8.1.8.1-160 version of ISS45 we are announcing certification of the ADK6.1.2 Self-Checkout Software.

The installation of the ADK 6.1.2 version will be installed using the following WIM images:

R6L-SCO-ADK612-02012019.wim (for R6L Hardware)

R6-SCO-ADK612-01312018.wim (for R6C Hardware)

XR7-RAP-ADK612-01312018.wim (for XR7 Rap)

These WIM files will install the OS and the ADK 6.1.2. The user will need to install the POS platform and the Transaction Broker.

The version of the Transaction Broker certified is as follows:

Retalix_ISS45_Application-6.01.02.01.05.exe

Retalix_ISS45_RAP_Application_6.01.02.01.04.exe

The ADK 6.1.2 software provides a new look to the SSCO interface as well as the Pick List Assist and Produce Assurance feature. A `prescottstart.bat` and `postscotstop.bat` are supplied with the image. It is recommended to apply any base ADK hot fixes before applying the Transaction Broker. (*Applying Hot Fixes after the Transaction Broker is installed may potentially overwrite the **prescotstart.bat** and the **postscotstop.bat** which are configured for the Pick List Assist and the Produce Assurance*)

For a more complete installation guide, please follow the following document:

R6L SSCO with ADK V6.1.2 Installation for ISS45.PDF

Note: There were several SSCO bug fixes included with this certification.

ISS45-1274 – Validate MTX Dlls

The updated MTX dll versions of Connected Payments are in this release of ISS45. This release was validated with the following **Connected Payments** dlls.

Verifone Terminals: Gold 39

- MTX_EPS.dll 828.7.21.86

Equinox Terminal: Gold 18

- MTX_EPS.dll 829.2.21.77

Verifone and Equinox:

- MTX_POS.dll 829.2.0.23
- MTX_POS_CPMX.dll 829.2.0.23
- MTX_POS_CPEQ.dll 829.2.0.23
- MTX_POS_WinEPS.dll 828.0.1.207
- MTX_POS_EMPTY.dll No versión

ISS45-1488 – Apply Windows Updates

The latest Windows Updates have been tested and applied in this release of the ISS45.

This release was tested with the available Windows updates applied on 03/26/2019.

- MFS1 - Windows 7 Profession SP1
- POS – POSReady 7 SP1



© NCR Corporation, 2019

NCR endeavors to ensure that the information in this document is correct and fairly stated but does not accept liability for any error or omission.

The development of NCR products and services is continuous and published information may not be up to date. It is important to check the current position with NCR. This document is not part of a contract or license, save insofar as may be expressly agreed.

NCR Corporation
2651 Satellite Blvd.
Duluth, GA 30096

P/N 89000936
PIN 45001/081