

Technical Bulletin

Fujitsu D22/D25 Display Driver Update

HW-TECH-07:06

March 13, 2007

A flaw with the D22/D25 MSR drivers was recently discovered that opens a window of opportunity for credit card information to mix across transactions.

The driver update that addresses the issue can be found on the StoreNext Dealer Support Web site on the [Drivers Page](#). The updated driver at this writing can be accessed directly by [clicking here](#).

Steps to update:

1. Follow instructions in Chapter 3 of the attached TeamPoS3000D22_D25_MSR_KeyLock.pdf document to Un-Install the old D22/25 MSR driver.
2. Reboot
3. Replace D22/25 keyboard/MSR driver files with those attached. These are usually found on TP3K Windows images in C:\TeamPoS3000_Software_Support\Drivers\Keyboards\D22 and D25 Keypad_MSR\Driver
4. Follow instructions in Chapter 2 of the [TeamPoS 3000 D22-D25 Keypad and MSR Driver Installation manual](#) available from the Hardware Manuals Page of the StoreNext Dealer Support Web site.

Regards,

Karen R. Castillo

Sustaining Engineering

FUJITSU Transactions Solutions Inc.

This document and information are supplied to StoreNext Retail Technologies personnel and third parties to assist them in doing business with StoreNext. They are not to be used or distributed for any other purpose.

StoreNext Retail Technologies LLC endeavors to ensure that the information in this document is correct and fairly stated, but does not accept liability for any error or omission.