



Subject: A760-2225 Printer on U-Scan

Overview

The A760-2225 printer (FTXS Part Number 90000755) is released and can be used on the U-Scan system. However a change to the Devices.INI file must be made to allow proper operation.

Problem

If the appropriate changes are not made to the Devices.INI file, and/or the Baud rate are not set correctly, the printer will not function correctly.

Solution

Modify the Devices.INI as follows:

File Location: C:\Cashier\Data\
File Name: Devices.INI

In the [NCR_7156] section of the Devices.INI file, add the following line:

NoIdPrinter=38

Save this modified file.

Verify printer Baud rate is set to 9600 Baud.

Restart Controller.

Done.

Sample partial listing from modified Devices.INI file:

```
[Devices]
DigiEnabled=1
DigiIRQ=5
DigiSharedAddress=140
DigiStartAddress=100
```

```
[NCR_7156]
PortNumber=5
Baud=9600
Parity=NONE
Length=8
StopBits=1
RxBuffer=200
TxBuffer=6000
FrankOffset=31
Use4610CheckData=FALSE
NoIdPrinter=38
```

←This line added

<u>INQUIRIES TO:</u>		DATE
Fujitsu Transaction Solutions Inc.		
Exchange: Sustaining Engineering	Sustaining Engineering	
Mail: Fujitsu USA04, Sustaining Engineering		
FAX: 858-731-4781 (7888-4781)	Product Manager	
Internet: SustainingEngineering@ftxs.fujitsu.com		
FTP: ftp://ftp.ftxs.fujitsu.com/	Author	
Original signature copies maintained by Sustaining Engineering.		