

A decorative horizontal bar with a grey background, featuring several overlapping squares in dark blue, red, and white, some with black outlines.

U-SCAN®

-  *U-Scan Release Notes*
-  *StoreNext Release 39*
- 
- 
- 



U-Scan Release Notes

Date of Issue	Product Identification Number	Part Number	Brief Description
March 2006	45001/103	89000289	Initial Release
June 2006	45001/103	89000311	Release 27
January 2007	45001/103	89000347	Release 39

**© Copyright StoreNext Retail Technologies LLC 1995-2007
All rights reserved**

This publication is protected by federal copyright law. No part of this publication may be reproduced or transmitted into any human or computer language in any form or by any means, stored in a retrieval system, transmitted, redistributed, translated or disclosed to third parties, or de-compiled in any way including, but not limited to, photocopy, photograph, electronic, mechanical, magnetic or manual without the express written permission of StoreNext Retail Technologies LLC or its licensors, if any. This document, notwithstanding the above, may be distributed in electronic or printed form to personnel who are employed by either (1) a StoreNext customer of the subject system of this document or (2) personnel from an authorized StoreNext dealer of the subject system of this document. All copies, so distributed and/or so authorized, shall contain a full copy of this copyright notice.

StoreNext Retail Technologies LLC endeavors to ensure that the information in this document is correct and fairly stated but does not accept liability for any error or omission. StoreNext Retail Technologies LLC makes no representation or warranties with respect to the contents hereof, and specifically disclaims any implied warranties of merchantability or fitness for a particular purpose or non-infringement. No commitments by StoreNext or its suppliers are made from this documentation which is provided for information only.

Development of StoreNext products and documentation is continuous: StoreNext Retail Technologies LLC reserves the right to revise this publication and to make changes from time to time in the contents hereof or in the products herein described or discussed without notice and without any obligation of StoreNext Retail Technologies LLC to notify any person or organization of such revision or changes. Information published in this document will likely become obsolete over time and it is recommended that users regularly check for updates and newer versions.

StoreNext Retail Technologies LLC has prepared this manual for use by users, authorized third parties and personnel of StoreNext Retail Technologies LLC as a guide to the proper installation, operation, customization and/or maintenance of StoreNext Retail Technologies LLC equipment and software. The drawings and specifications contained herein are the property of StoreNext Retail Technologies LLC and/or its licensors.

Third-party products, services, or company names referenced in this document may be trademarked or copyrighted by their respective owners, and are for identification purposes only.

Copyrights, trademarks and license agreements shall be governed and construed in accordance with the laws of the State of Texas and the Federal Arbitration Act, and shall benefit Retailix, its successors, and assigns.

Address comments and corrections to:

StoreNext Retail Technologies LLC
Software Program Director
6100 Tennyson Parkway
Suite 130
Plano, Texas 75024

How to Upgrade

This section describes the software upgrade method for this build..

CD Installation

CD Installation is the traditional method for installation. It requires that you have the installation CD(s) on hand. After a successful CD installation, all changes related to the new release will be available and the software version will be changed to reflect the newly installed version. In this case, the software version will become StoreNext39_551_STNXT1.3.9_Retalix60-WPSCO3_56C.

Note: The resulting installation will have blank or default data files, except where the installation Field Engineer has ensured to preserve the desired data files. Also, local configuration settings (station type, left/right configuration, etc.) will need to be re-applied.

Refer to the StoreNext Software Service Guide for detailed instructions on how to upgrade the software. This guide is available from National Tech Support (Tech Web) for Field Engineers or from the Fujitsu Software Project Manager for store contacts.


New Features / Enhancements

- (23364) Changed the default settings for the **Scanner Scale** and **Coin Dispenser**.
- (25111) Added support for the **Rohs Compliant iPad**.
- (26502) Changed the **color of the Customer Station background** when security is disabled.
- (26505) Added support for the **TPG 794 printer**.
- (27506) Changed the registry value for **BagScaleUnstableWeightTimeThreshold** to 8000 (decimal).

Fixes

- (17285) Corrected the sequence for **coupon processing**.
- (17322, 18699) Resolved the issue where a **price required** or **quantity required** item could not be **voided**.
- (23331) Added proper handling of **code128 barcodes**.
- (23347) Resolved the issue where using the **Manager Override** card in **Local Direct Mode** was not working.
- (25183) Added new **open/close lane functionality** to the Local Direct Mode screen and new frame image as well.
- (25751) Add the following setting to the registry:
"SendRcvCoinMsgsWhenDisabled"=dword:00000000"
- (26277) Changes made for the new firmware on the **F53 Bill Dispenser**.
- (26284) Modified the error state of the **F53 Bill Dispenser** to keep the most important error and to display all the errors.
- (26291) Corrected system behavior. The **F53 Bill Dispenser** now recovers from a dispense error which takes it offline.
- (26497) Resolved the issue where items that have the **Price Verify** flag set on the PLU record cannot be rung at the Attendant Station.
- (26503) Corrected the way '**Assume Quantity**' items was being handled.

- (27168) Corrected visibility conditions for the **skip bagging button** and **skip bagging limit reached** image to work with current IEMM version.
- (26263) Added resetting of the '**uiNumberOfSkipItemAllowed**' upon starting a new transaction.
- (27478) Resolved the issue regarding when the weight on the scanner was at zero, it was not recognized by the system.



© StoreNext Retail Technologies LLC 2007

StoreNext Retail Technologies LLC endeavors to ensure that the information in this document is correct and fairly stated but does not accept liability for any error or omission.

The development of StoreNext products and services is continuous and published information may not be up to date. It is important to check the current position with StoreNext. This document is not part of a contract or license save insofar as may be expressly agreed.