

Technical Bulletin

USB Software Enablement (HASP) Keys for ISS45 8.1.8.1 Required

POS-TECH-19:06 Issue 2
June 5, 2019

ISS45 8.1.8.1-050 and later POS systems need the USB version of the Software License Enablement keys (aka "HASPs").

Most of the old parallel HASPs are out of the installed base at this point, but there are some still out there. When you upgrade the software to 8.1.8.1, make sure that the store has USB keys.

The previous HASP driver did not support 64-bit systems, and an updated HASP driver was deployed with 8.1.8.1. This new driver, however, does not support the old parallel HASP keys, so the USB keys are required for these newer ISS45 software versions.

Note that the new HASP driver is used in ALL 8.1.8.1 systems, so the USB HASP will be required regardless of whether the system is installed as 32-bit or 64-bit.