

Technical Bulletin

Magellan 8500Xt Firmware Upgrade

POS-TECH-09:25
November 17, 2009

The Magellan 8500Xt now has stabilized firmware that has been certified with both ScanMaster and ISS45. StoreNext has released orders and is commencing shipments of the 8500Xt now that dealers have access to this firmware.

This latest version of firmware from Datalogic Scanning is available on the StoreNext Dealer Support Web site. It can be accessed from the Support Page by selecting "Drivers, Firmware ..." and then selecting [Datalogic Firmware FTP](#). The drivers and documentation for loading can be found in the "8500Xt" folder.

Do not install the 8500Xt without upgrading this firmware! The store is certain to have problems.

Datalogic Scanning is cutting the new firmware into manufacturing, but this process may take as long as two or three weeks before new 8500Xt units will leave Datalogic Scanning with the new firmware pre-installed. StoreNext will notify dealers as soon as the units are shipping to spec. Until then, dealers will need to flash the updated firmware into the 8500Xt.

Most dealers have the necessary flash cable for this process. If you do not have this cable, order:

PIN	Item	Price	Inst	Maint
PSC-8-0730-49	Datalogic Cable, Test Port, RS-232, 9 pin "D" connector, Socket, Power off external brick, RoHS, 5 ft. Test Port Doctor (TPD) Direct-Connect cable to PC, supports 8100 / 8200 / 8300 / 8400 / 8500 / 8500Xt / 9500 / 2200VS / 2300HS. Used to update flash memory with firmware.	\$ 25 Dealer Net Price: \$15	N/A	N/A

This document and information are supplied to StoreNext Retail Technologies personnel and third parties to assist them in doing business with StoreNext. They are not to be used or distributed for any other purpose.

StoreNext Retail Technologies LLC endeavors to ensure that the information in this document is correct and fairly stated, but does not accept liability for any error or omission.