



Subject: Genesis Bumpers on NextGen U-Scan

Overview

The mold for the existing Next Gen bumpers has broken. Until a new mold has been created by the supplier, the mold for Genesis bumpers will be used for Next Gen bumpers as a temporary measure.

Solution

The new part numbers below are alternatives to the existing bumper part numbers, until such time as the supplier can provide the original bumpers using a regenerated mold.

These new parts are not interchangeable with the original.

Part Number	Description	Alternative for
11002931	NG Bumper, Side	11000802 – BUM-1018A
11002932	NG Bumper Kit, 26.3	11000803 – BUM-1019
11002933	NG Bumper Kit, Rear	11000804 – BUM-1020
11002934	24" Cash Rear Bumper NG	11000805 – BUM-1024
11002935	NG 2 Bumper Kit, U-Scan 3	11000806 – BUM-1028
11002936	NG 2 Bumper Kit, U-Scan 5	11000807 – BUM-1029
11002937	NG Scan Door Bumper Kit 17.5	11000808 – BUM-1031
11002940	37" Cashier Rear Bumper	11001417 – BUM-1022
11001908	Carousel - Primary Bumper, Kit	11000809 – BUM-1032
11001910	Carousel Primary Bumper	
11001905	Carousel Spacer, 1.0"	
11001909	Carousel – Secondary Bumper, Kit	11000810 – BUM-1033
11001911	Carousel Secondary Bumper	
11001905	Carousel Spacer, 1.0"	

To assist with Parts Identification, pictures are available for the above kits. These pictures can be located on the FTP site below in the following path: This was done so this bulletin will not become too large. The zip file of the pictures is 7M in size.

<ftp.ftxs.fujitsu.com>

/pos/possustaining/Retail/U-ScanNextGen/PSB-08-057 BumperParts.zip

INQUIRIES TO:		DATE
Fujitsu Transaction Solutions Inc.		
Exchange:	Sustaining Engineering	_____
Mail:	Fujitsu USA04, Sustaining Engineering	_____
FAX:	858-731-4781 (7888-4781)	_____
Internet:	SustainingEngineering@ftxs.fujitsu.com	_____
FTP:	ftp://ftp.ftxs.fujitsu.com/	_____
	Author	_____
Original signature copies maintained by Sustaining Engineering.		