



Subject: New BIOS for TeamPoS 3000 XL and XT Terminals

Overview

A new BIOS is being released for the TeamPoS 3000 XL and XT terminals for the 11000021 motherboard. This is a non-mandatory change that will be cut into production upon approval.

Old BIOS = P09, P013, and P016 New BIOS = P017

* Note: See bulletin PSB-08-013 for changes in earlier BIOS.

The new BIOS has enhancements from P16 to P17 for customers who want to support:

1. Windows Vista installation. An executable file is attached with P17, "Slp20.exe" Setting slp20.exe to 1 enables marker and public key. Setting slp20.exe to 0 disables marker and public key.
2. Disable/Enable Quick Boot function. "Boot Menu" item has been added in the BIOS. If set to "Disable," Quick Boot menu during POST will not display nor work when pressing F12. If set to "Enable," Quick Boot menu functions as normal when pressing F12.

Solution

Install new BIOS using WIN Flash utility, CD ROM, Floppy, or USB key.

The new P17 BIOS fixes the issues above and can be downloaded from the FTP site. This zip file also contains instructions for loading the BIOS. Utilities for loading the BIOS can be found in the BIOS folder.

Site: <ftp://ftp.ftxs.fujitsu.com>
 Path: pos/possustaining/retail/TeamPoS3000XL/BIOS/BIOS_P17.zip
 or pos/possustaining/retail/TeamPoS3000XT/BIOS/BIOS_P17.zip

| <u>INQUIRIES TO:</u> | | DATE |
|--|--------|-------|
| Fujitsu Transaction Solutions Inc. | | |
| Exchange: Sustaining Engineering | _____ | _____ |
| Mail: Fujitsu USA04, Sustaining Engineering | _____ | _____ |
| FAX: 858-731-4781 (7888-4781) | _____ | _____ |
| Internet: SustainingEngineering@us.fujitsu.com | _____ | _____ |
| FTP: ftp://ftp.ftxs.fujitsu.com/ | _____ | _____ |
| | Author | |
| Original signature copies maintained by Sustaining Engineering. | | |