



Subject: U-Scan Attendant Station Power Strips

Overview

Due to RoHS compliance, the current Power Strips in the U-Scan Attendant Station are no longer available. There are 2 versions of the Power Strip in current use, they are both replaced by using 2 each of the new Power Strip.

New Part #	Description	
11001957	Power Strip, 5 Outlet, with Ground Wire	

Old Part #	Description	Replaced By
MIS-1005	Power Strip, 32", 10 Outlet	11001957 (Qty 2)
MIS-1025	Power Strip, 24", 8 Outlet	11001957 (Qty 2)

All new production will contain 2 of the new Power Strips, 11001957.
If an existing Power Strip must be replaced, 2 of the new Power Strips must be used in its place.

INQUIRIES TO:		DATE
Fujitsu Transaction Solutions Inc.		
Exchange:	Sustaining Engineering	_____
Mail:	Fujitsu USA04, Sustaining Engineering	_____
FAX:	858-731-4781 (7888-4781)	_____
Internet:	SustainingEngineering@us.fujitsu.com	_____
FTP:	ftp://ftp.ftxs.fujitsu.com/	_____
Original signature copies maintained by Sustaining Engineering.		