

Subject: Genesis Site Prep Error

Overview

An error has been found in the U-Scan Genesis Site Prep manual that may lead installers to improperly install units.

Document affected:

V06_Genesis_SitePrep.pdf

Revision 6, released November 7, 2008

Document Location:

Chapter 2 – Site Layout – 5

Figure 2.3

The illustration (see below), indicates that Genesis Robots installed back to back only need 5cm (2 inches) service clearance between rows. This is not correct. The correct dimension is 30cm (12 inches).

This change will be made in a future revision of the document (no anticipated data at this point).




Figure 2.3 Four U-Scan4 Customer Stations with Attendant Station (C)

INQUIRIES TO:		DATE
Fujitsu Frontech North America	_____	_____
Exchange: Sustaining Engineering	Sustaining Engineering	_____
Mail: Fujitsu USA04, Sustaining Engineering	_____	_____
FAX: 858-731-4781 (7888-4781)	Product Manager	_____
Internet: SustainingEngineering@us.fujitsu.com	_____	_____
FTP: ftp://ftp.ftxs.fujitsu.com/	Author	_____
Original signature copies maintained by Sustaining Engineering.		