

Technical Bulletin

Drivers License ID State Support for ScanMaster and ISS45

POS-TECH-13:09
April 17, 2013

ISS45 8160-060+ and ScanMaster 2.08.00-050+ support drivers license ID scanning. Datalogic imagers using Datalogic OPOS 1.12.0084 are the only imaging devices supported by Retalix.

Drivers licenses for the following states are supported for imaging. All these states have been tested with actual examples of the appropriate DLs:

- Alaska
- Hawaii
- Illinois
- Indiana
- Kentucky
- Maryland
- Nevada
- Minnesota
- New Hampshire
- New Jersey
- New York
- Ohio ¹
- Pennsylvania
- Washington
- West Virginia

Datalogic has provided sample images for the following states, and support for these DLs is assumed to work correctly:

- Alabama
- Arizona
- Arkansas
- Arkansas
- California
- Colorado
- Connecticut
- District of Columbia
- Florida
- Georgia
- Idaho
- Iowa
- Kansas
- Maine
- Massachusetts
- Michigan
- Mississippi
- Nebraska
- North Carolina
- Oklahoma
- Oregon
- South Dakota
- Tennessee
- Texas
- Utah
- Vermont
- Wisconsin
- Wyoming

States and territories where support is not currently provided or status is unknown are:

- Delaware
- Louisiana
- Missouri
- Montana
- New Mexico
- North Dakota
- Puerto Rico
- Rhode Island
- US Virgin Islands

¹ Full Support for Ohio was first provided with ScanMaster 2.09.00-050. Ohio support in ISS45 will be provided in an 8160 and/or 8170 update.

Simply stated, unless your state is DE, LA, MS, MT, NM, ND, RI, or the territory is Puerto Rico or the US Virgin Islands, the expectation is that driver's license ID will work. It is important to note that some states have changed their 2-D barcode layouts one or more times, so support may be limited to specific issue date ranges.

Our preference is to test real-world driver's licenses. Since states do not provide samples, Retalix requests high-resolution front-and-back examples from dealers wanting to add states to the supported list.

Please e-mail such examples to Heather.Blanarik@Retalix.com.

