

Technical Bulletin

NCR 7878 Imager Accessory — Certification and Installation Update and Instructions

POS-TECH-14:03
February 11, 2014

The NCR 7878 imager option (Kit 7878-K150) has been certified under ScanMaster V2.09.00-060+ and ISS45 V8.1.7.0-050+.

The NCR 7878-K150 Imaging Kit was installed in the NCR 7878-2001 scanner/scale.

- Follow the 7878-K150 Imaging Assembly Kit Instructions Issue B. Click on the link provided below for everything you need.
 - Note: some of the pictures are outdated and did not reflect correct picture of kit parts received.
 - You can also now order the 7878 scanner/scale with the imager unit pre-installed, using a package that includes the imager as a feature code (NCR-7878-F150) See the NCR POS Hardware Configuration and Pricing bulletin for details.
- The minimum required firmware version is 497-0472618.
- To check the Firmware version of scanner follow page 16.
- To upgrade the 7878 scanner/scale to the minimum version listed above use the USB Flash Drive Method documented in the installation guide on page 21.
- On pages 24-28 follow the sequence to program the imager.
- Pages 29-31 list the default symbologies and the other symbologies that can be enabled if needed.
- **ScanMaster** — to successfully scan a Driver's License you will need to edit the registry: HKEY_Local_Machine\Software\OLEforRetail\ServiceOPOS\Scanner\NCRScanner.7872\Model\LabelID.
 - Change the **1** to **0**
 - Note: the profile supported is NCRScanner.7872 using Model=NCR 7878 and Connection Type = USB
- **ISS45** — no changes are required to the default install for a driver's license to scan.

[Click Here](#) to access everything you need, including documents, firmware and the firmware upgrade tool.