

Technical Bulletin

U-Scan Repair Alternative — Circuitech

SC-TECH-06:02 – Issue 2

February 5, 2007

Circuitech has expanded its options as a repair source for U-Scan Bill Dispenser Units.

Circuitech has been in business for over 10 years and is fully certified by Fujitsu to repair both the De La Rue NMD 50 and Fujitsu F53 Bill Dispensers. Circuitech provides a 90-day warranty on all repairs and states that over 80% of their repair work is turned around in 5 days or less.

Repair of the bill-dispenser units, if provided intact to Circuitech, includes the following services:

1. Complete cleaning of unit
2. Replacement of belts
3. Replacement of sensors, gears etc. as required
4. Rebuild of PCB if necessary
5. Rebuild of cassette as needed — bill denomination sets stay the same as received
6. Comprehensive testing of unit upon completion of cleaning and rebuild
7. 90-day warranty from date product ships from Circuitech dock
8. Foam in place packaging that can be reused for future shipments of similar units

Circuitech strongly recommends that users retain any dispenser packaging to minimize the risk of damage from inadequate packaging. For example, dealers should never use “peanut” packaging for these products. Each dispenser full assembly should contain foam packaging on all four sides so there can be no movement in the box during shipping.

StoreNext dealers should work directly with Circuitech when BDU repair is required. To contact Circuitech:

Mark Matteson
Circuitech
535 Minnehaha Ave. West
St. Paul, MN 55103

651.298.8444 (V)
651.298.8221 (FAX)
www.circuitech.com

FUJITSU F53 BILL DISPENSER REPAIR

The pricing for complete repair of the Fujitsu F53 Bill Dispenser cassette or cassette complete assembly for U-Scan is:

Complete Assemblies:

- KD03064-B005 — 3-denomination Fujitsu F53 complete dispenser assembly: \$425.00
- KD03235-B006 — 2-denomination Fujitsu F53 complete dispenser assembly: \$350.00

This document and information are supplied to StoreNext Retail Technologies personnel and third parties to assist them in doing business with StoreNext. They are not to be used or distributed for any other purpose.

StoreNext Retail Technologies LLC endeavors to ensure that the information in this document is correct and fairly stated, but does not accept liability for any error or omission.

The prices supplied above are for the complete dispenser assembly, including the Main Dispenser Unit, 2 or 3 cassettes, PCB/circuit board and U-Scan type top unit. It is assumed that most dealers will remove the complete assembly, replace with a complete assembly and send Circuitech the complete unit. If there are field-service groups that wish to send in just a U-Scan top unit, PCB, or cash cassette, Circuitech will provide pricing for each component upon request.

DE LA RUE NMD 50 BILL DISPENSER REPAIR

The pricing for repair of the De La Rue NMD 50 Bill Dispensers is below:

Complete Assemblies:

- Single denomination NMD 50 \$ 350.00
- Two denomination NMD 50 375.00
- Three denomination NMD 50 400.00

Individual Components:

- One cassette extension \$ 250.00
- Note Qualifier Unit 350.00
- Note Feeder Unit 325.00
- Note Feed Controller 225.00
- Central Machine Controller 275.00
- Note Transport 300.00

Please note that:

- Circuitech will not repair any broken plastic parts on the NMD 50. The Dealer may incur an up-charge to replace plastic frames and so forth
- Circuitech highly recommends the use of the original packaging when shipping the NMD 50 dispenser to minimize the chance of costly damage during shipping to and from the repair facility.

StoreNext dealers should work directly with Circuitech when BDU repair is required. To contact Circuitech:

Mark Matteson
Circuitech
535 Minnehaha Ave. West
St. Paul, MN 55103
651.298.8444 (V)
651.298.8221 (FAX)
www.circuitech.com

