

Wrong, Wrong, Wrong!

September 23, 1996

I was so discomposd about all these new products — or was it Bernard — that I managed to screw up the administrative end pretty thoroughly. No, nothing really serious (prices didn't go up or anything), but please be aware of the following:

1. On MB 1100, one of the Q&A answers says "You can't have a **4** lane **ISS45 Express** store." That's BS: it's a **5** lane Express store you can't have.
2. Also on MB 1100, another question discusses the Fleming Lease Program in relation to non-Fleming-member accounts. Although the Fleming **Program** can be used where useful for non-Fleming members, the **Lease** program is not available for such grocers.
3. On the SlimScan 1200 bulletin, (MB 1102) the PIN for the (most important PIN, of course) SlimScan 1200 unit itself is incorrect. Don't use it or you'll get an empty box along with an invoice for the freight. Instead, use **PB600064**. Then at least the freight bill will be worth it.
4. Also on MB 1102, the PIN for the brochure pack should be **45008/001**, not 45007/001.
5. Oh yes, and if you come to the ISS45 Service and Support Course scheduled for December 16, you'll get an empty classroom and an invoice for your plane ticket. The right days for the course are December 9 — December 13.
6. Oops: version 7.3.0 is **not** on the bulletin board at this point. Too big to load down anyway.

KEY POINTS ON **ISS45 EXPRESS** :

- Yes, the Software **is** included in the price of the **ISS45 Express** packages. The package price includes the hardware and the software.
- All **ISS45 Express** systems presume that there is a single back office PC. Since that PC will be used for the Controller Service, there is no PIP (Controller/Terminal) in the front end.
- On the **ISS45 Express** packages, when the configuration says "No ICL PCs", that's exactly what it means. There won't be a PC shipped either for back office purposes nor for the CPUs of the terminals at the front end. So, for example, if you don't order a package with ICL PCs for a 3-lane store, you'll need to supply four PCs for that installation, one for the back office and one for each of the lanes.

I've enclosed brand spanking new Issue 2 versions of the offending material. Wishing you a better Monday than **I** had...

Tony

Tony van Seventer

(Former) Director: Supermarket Systems