

## Technical Bulletin

### ScanMaster REGCHANGE.EXE Utility

SM-TECH-09:02  
February 10, 2009

Please be advised:

In the past some dealers may have used the REGCHANGE.EXE utility after having “cloned” a POS to make changes to the registry to reflect the new POS workstation.

Although running REGCHANGE.EXE will correct many registry entries, this utility does not address all entries such as the SID. The preferred method remains loading each lane from scratch, although we realize this may be time-consuming when many lanes are involved.

StoreNext does not support or recommend any specific cloning method, even though third-party utilities such as Microsoft’s SYSPREP have been used by some with apparent success in the field.

This document and information are supplied to StoreNext Retail Technologies personnel and third parties to assist them in doing business with StoreNext. They are not to be used or distributed for any other purpose.

StoreNext Retail Technologies LLC endeavors to ensure that the information in this document is correct and fairly stated, but does not accept liability for any error or omission.