

## Technical Bulletin

### TPG Printer OPOS Versions for ScanMaster and ISS45

POS-TECH-10:05  
February 3, 2010

The following version of TPG OPOS must be used depending on the POS with which it is installed.

#### SCANMASTER

Starting with ScanMaster 2.01.02-050 use the **TPG OPOS v1.5.6**. This driver is located:

- On the current ScanMaster CD under the \Drivers\TPG OPOS and 776 USB Driver folder
- On the StoreNext Dealer Web site: from the Support Page, go to the Drivers and Firmware Page where you will find a TPG listing. Folders for ISS45 and ScanMaster are currently available. You may currently [Click Here](#) to go directly to the ScanMaster folder.

Do not use TPG OPOS v18036 for ScanMaster installs at this time due to check printing and endorsing problems.

Note: ScanMaster V1 does not use OPOS so this bulletin does not apply to ScanMaster V1.

#### ISS45

The TPG OPOS driver currently used on ISS45 is **InstallTPG\_OPOSV18036.exe**

A problem with the earlier TPG OPOS driver causes a hyphen or dash (“-”) to appear in the account number when processing certain Bank of America checks. This additional character also appears in the WinEPS journal file.

The new driver with proper operation is provided:

- On the current ISS45 V7 and V8 CD-ROM releases
- On the StoreNext Dealer Web site: from the Support Page, go to the Drivers and Firmware Page where you will find a TPG listing. Folders for ISS45 and ScanMaster are currently available. You may currently [Click Here](#) to go directly to the ISS45 folder.

This document and information are supplied to StoreNext Retail Technologies personnel and third parties to assist them in doing business with StoreNext. They are not to be used or distributed for any other purpose.

StoreNext Retail Technologies LLC endeavors to ensure that the information in this document is correct and fairly stated, but does not accept liability for any error or omission.