

# TECHNICAL BULLETIN

## HASP Key Requirements for ISS45 8170-150 Self-checkout, ProLogic (S&H/YOU Tech etc.)

May 5, 2016

ISS45-TECH-14:06 Issue 2

This Issue 2 updates the ordering requirements for HASP key changes to enable these interfaces.

Changes to the HASP key system with the 8170-150 release have been made that require the keys to enable all self-checkout interfaces as well as the ProLogic (also known as S&H, GreenPoints, YOU Technologies etc.) interface.

A reminder note has been provided on the 8170-150 Release Table and the change is also discussed in the 8170-150 Release Notes manual.

- Unless the key is properly set, 8170-150 will not support any self-checkout interfaces, including NCR SSCO or the U-Scan system.
- The ISS45 system will not communicate with the ProLogic system or any of its predecessors unless the HASP key is set for this function as of 8170-150.

Key updates are not required for these software releases otherwise.

HASP updates will be provided with these functions upon receipt of a Purchase Order accompanied by a complete SKIF (see special SKIF requirements below).

- **Do not order the interface itself!** – If this type of key update is required, the customer has already purchased the necessary interface license. It just needs to be added to the HASP.
- **Instead** – Order one (1) of the following item for each HASP to be updated:

PID / PIN	Item	Price
G330-0190-KU00 (was 45000/010)	Software License Enablement Key (HASP), Update Service for \$0 Software, per Key <small>Required for updates to a License Enablement/Protection Key (HASP) for \$0 software orders. For example, adding electronic payments software options at \$0, ISS45 MFS-LFS Swaps etc. This item is NOT REQUIRED when purchasing priced software options or license additions. ¶-Order 2@ for dual-key system. When keys are updated, both keys from the original key pair must be updated. ¶-For email updates to original keys only. Do not order this item if the physical HASP keys need replacement. No new keys will be provided by ordering this item. If new keys are needed, select instead G330-0190-0000 (Software License Enablement Key (HASP), Replacement Service and Shipping, per Key). ¶-Quantities required are per order. If multiple PINs on an order for one site require this PIN, only a quantity of 1 (for single-key systems) or 2 (for dual-key systems) of this key service PIN will be required. For example, if several electronic payments options are ordered for a dual ISS45 MFS1/MFS2 system with a Connected Payments subscription, only 2 of this item need to be ordered. ¶-The requirement for this item will be waived if paid (non-zero dollar) software options are simultaneously purchased with the \$0 software items that normally require this item. For example, if a MFS-&gt;LFS swap (this service fee normally required) is ordered at the same time as a CCTV interface (MRP of \$995) the CCTV interface item on the P.O. will waive the need for the key service fee item.</small>	Dealer Net: \$35

...continued on following page

- The order must be accompanied by a complete SKIF. To enable fulfillment of your order, make sure the SKIF includes:
  - The customer site name including the store number if applicable.
  - The Channel Partner's original P.O. number or NCR/Retalix/StoreNext Sales Order number under which the interface (the one that is now being added to the Software License Enablement Key) was originally purchased. Unless this information is provided, NCR will not be able to verify that the site is licensed for the requested interface, and the order will be declined.
  - If the store is registered with two HASP keys, both current HASP key numbers must be listed on the SKIF.
  - The SKIF must have all the site's existing key features checked in the "Already Has" column. Use the previous SKIF from your files or the POS system's Key Report to populate the SKIF correctly. Do not put the ProLogic or self-checkout interface features needed in this column, since the key does not "Already Have" them set.
  - Check the box in the "Adding Now" column for the ProLogic Interface or for the self-checkout interface that the customer had previously purchased but is not currently on the HASP. (Note: If the interface product has been withdrawn for new sale (like the U-Scan Interface) and a check-box is absent for the item, enter "Please Add" in the cell that otherwise would have provided the check-box.)
- Follow the normal ordering process with NCR Order Entry. The HASP key set and store license will be matched against the store's original orders; the HASP keys will be updated if the SKIF information enables confirmation that the site is licensed for the requested interfaces.