



Subject: New P11 BIOS for TeamPoS 3000 XL2

Overview

A new version of BIOS (P11) has been released for the TeamPoS 3000 XL2 (Yosemite) terminal. The change from P10 to P11 is to allow Windows 7 installation. The new BIOS is transparent to all non Windows 7 users.

The updated BIOS is compatible with all previous versions.

The part number of the Motherboard (11001590) and the PIN for the TeamPoS 3000 XL2 are not being changed.

Impact

- Production
 - All units manufactured after July 12, 2010 have this change implemented.
- Installed Units No Impact.
 - If a customer updates to Windows 7 on units with BIOS at less than version P11, will need to be updated at or before the Windows update.
- Repair Center
 - All motherboards returned for repair should be updated to the latest (P11) BIOS.
- Service Spares No Impact. No stock update is requested or implied.

<u>INQUIRIES TO:</u>		DATE
Fujitsu Frontech North America		
Exchange: Sustaining Engineering	_____ Sustaining Engineering	_____
Mail: Fujitsu USA20, Sustaining Engineering	_____	_____
FAX: (949) 458-6257	_____ Product Manager	_____
Internet: SustainingEngineering@us.fujitsu.com	_____	_____
FTP: ftp://ftp.ftxs.fujitsu.com/Pos/PosSustaining/	_____ Author	_____
Original signature copies maintained by Sustaining Engineering.		